

	Type	Hits	Search Text	DBs	Time Stamp	Error Com m e n t s t i o n	Ref #
1	BRS	1	10/735770	US-PGPUB; USPAT	2005/03/17 17:44		S1
2	BRS	2663	(349/43,106,108,110).ccds.	US-PGPUB; USPAT	2005/03/16 17:56		S9
3	BRS	2248	S9 and @ad<"20021217"	US-PGPUB; USPAT	2005/03/18 19:12		S10
4	BRS	1086	(349/106,108).ccds.	US-PGPUB; USPAT	2005/03/16 18:00		S11
5	BRS	947	S11 and @ad<"20021217"	US-PGPUB; USPAT	2005/03/16 18:00		S12
6	BRS	1	("5859683").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 18:33		S13
7	BRS	9	("6118505").URPN.	USPAT	2005/03/16 18:34		S14
8	BRS	5	("5499124" "5933208" "5943107" "6008872" "6118505").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 18:37		S15
9	BRS	1	("5859683").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 18:37		S16
10	BRS	1	("6191835").URPN.	USPAT	2005/03/16 18:38		S17
11	BRS	5	(US-5396356-\$ or US-6118505-\$ or US-6191835-\$ or US-6008872-\$ or US-5933208-\$).did.	USPAT	2005/03/16 18:47		S18
12	BRS	9	("4636038" "5229644" "5251071" "5327001" "5495354" "5585951" "5641974" "5786042" "5818550").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 18:47		S19
13	BRS	9	("4636038" "5229644" "5251071" "5327001" "5495354" "5585951" "5641974" "5786042" "5818550").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 19:18		S20
14	BRS	10	choi-woo-ho.in.	US-PGPUB; USPAT; USOCR	2005/03/16 19:19		S21
15	BRS	74	hyundai.as. and "349"/\$.ccds.	US-PGPUB; USPAT; USOCR	2005/03/16 19:19		S22
16	BRS	1	("5859683").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 19:23		S23
17	BRS	9	("6118505").URPN.	USPAT	2005/03/16 19:23		S24
18	BRS	12	("4636038" "5229644" "5641974" "5742365" "5751381" "5781254" "5784133" "5798744" "5850271" "5851411" "5852485" "5854663").PN.	US-PGPUB; USPAT; USOCR	2005/03/16 19:44		S25
19	BRS	1088	(349/106,108).ccds.	US-PGPUB; USPAT	2005/03/17 12:35		S26
20	BRS	1089	349/43.ccds. and (not S26)	US-PGPUB; USPAT; USOCR	2005/03/17 12:35		S27
21	BRS	874	S27 and @ad<"20021217"	US-PGPUB; USPAT; USOCR	2005/03/17 12:36		S28
22	BRS	347	(wiring adj structure).ti.	US-PGPUB; USPAT	2005/03/17 12:38		S31
23	BRS	10	S31 and "349"/\$.ccds.	US-PGPUB; USPAT	2005/03/17 12:45		S32
24	BRS	1	10/653914	US-PGPUB; USPAT	2005/03/17 13:29		S33

	Type	Hits	Search Text	DBs	Time Stamp	Error Com m m e n t s	Ref #
25	BRS	616	S28 and @pd<"20030619" and (gate adj electrode) (US-5396356-\$ or US-6118505-\$ or US-6191835-\$ or US-6008872-\$ or US-5933208-\$ or US-6002462-\$ or US-5926702-\$ or US-6365916-\$ or US-6707513-\$ or US-6337723-\$).did.	US-PGPUB; USPAT	2005/03/17 13:30		S35
26	BRS	10		USPAT	2005/03/17 15:43		S36
27	BRS	6393	(gate adj electrode) adj4 over (gate adj insulation adj layer)	USPAT	2005/03/17 15:45		S37
28	BRS	298	S37 and "349"/\$.ccls.	USPAT	2005/03/17 15:44		S38
29	BRS	25	(gate adj electrode) adj4 over adj4 (gate adj insulation adj layer)	USPAT	2005/03/17 15:45		S39
30	BRS	2	("5731856" "6222600").PN.	US-PGPUB; USPAT; USOCR	2005/03/17 15:49		S40
31	BRS	241	349/46-47.ccls.	US-PGPUB; USPAT; USOCR	2005/03/17 15:49		S41
32	BRS	149	S41 and (not 349/43.ccls.)	US-PGPUB; USPAT; USOCR	2005/03/17 15:49		S42
33	BRS	14	("4519678" "4723838" "4770498" "4776673" "4869576" "4904060" "5051800" "5153754" "5288591" "5299041" "5691782" "5731858" "5757449" "5796455").PN.	US-PGPUB; USPAT; USOCR	2005/03/17 15:53		S43
34	BRS	6	("4948231" "5223961" "5233211" "5552909" "6057904" "6319760").PN.	US-PGPUB; USPAT; USOCR	2005/03/17 16:38		S44
35	BRS	21	(US-5396356-\$ or US-6118505-\$ or US-6191835-\$ or US-6008872-\$ or US-5933208-\$ or US-6002462-\$ or US-5926702-\$ or US-6365916-\$ or US-6707513-\$ or US-6337723-\$ or US-6222600-\$ or US-5691782-\$ or US-6608658-\$ or US-6319760-\$ or US-6057904-\$ or US-5552909-\$ or US-4948231-\$ or US-5223961-\$ or US-5233211-\$ or US-5936292-\$ or US-5300449-\$).did.	USPAT	2005/03/17 17:25		S45
36	BRS	5	("5499124" "5933208" "5943107" "6008872" "6118505").PN.	US-PGPUB; USPAT; USOCR	2005/03/17 17:32		S46
37	BRS	123	hyundai.as. and (gate adj line)	US-PGPUB; USPAT; USOCR	2005/03/17 17:32		S47
38	BRS	26	S47 and "349"/\$.ccls.	US-PGPUB; USPAT; USOCR	2005/03/17 17:33		S48
39	BRS	773	philips.as. and (color adj filter)	US-PGPUB; USPAT	2005/03/17 17:44		S49
40	BRS	277	S49 and (gate adj electrode)	US-PGPUB; USPAT	2005/03/17 17:44		S50
41	BRS	237	S50 and (pixel adj electrode)	US-PGPUB; USPAT	2005/03/17 17:45		S51

	Type	Hits	Search Text	DBs	Time Stamp	Error Com m e n t s	Ref #
42	BRS	169	\$51 and (shield (black adj matrix) (black adj mask)) ("4470667" "4654117" "4704559" "4994434" "5003356" "5182620" "5287208" "5302987" "5389492" "5396262" "5398126" "5414278" "5414283" "5414547" "5418635" "5419991" "5422293" "5426523" "5445898" "5446562" "5453857" "5457553" "5463230" "5463484" "5528209" "5532180" "5539219" "5568289" "5585951" "5641974" "5650358" "5757445" "5818550" "5847720" "5886365").PN.	US-PGPUB; USPAT	2005/03/17 17:45		\$52
43	BRS	35		US-PGPUB; USPAT; USOCR	2005/03/17 17:59		\$53
44	BRS	6	("6365916").URPN.	USPAT	2005/03/17 18:06		\$54
45	BRS	2665	(349/43,106,108,110).ccls.	US-PGPUB; USPAT	2005/03/18 19:12		\$56
46	BRS	415	\$56 and @ad>"20021217"	US-PGPUB; USPAT	2005/03/18 19:12		\$57
47	BRS	2665	(349/43,106,108,110).ccls.	US-PGPUB; USPAT	2005/03/18 19:13		\$58
48	BRS	415	\$56 and @ad>"20021217"	US-PGPUB; USPAT	2005/03/18 19:13		\$59
49	BRS	123	hyundai.as. and (gate adj line)	US-PGPUB; USPAT; USOCR	2005/03/18 19:13		\$65
50	BRS	241	349/46-47.ccls.	US-PGPUB; USPAT; USOCR	2005/03/18 19:13		\$64
51	BRS	277	\$66 and (gate adj electrode)	US-PGPUB; USPAT	2005/03/18 19:13		\$67
52	BRS	237	\$67 and (pixel adj electrode)	US-PGPUB; USPAT	2005/03/18 19:13		\$68
53	BRS	347	(wiring adj structure).ti.	US-PGPUB; USPAT	2005/03/18 19:13		\$62
54	BRS	773	philips.as. and (color adj filter)	US-PGPUB; USPAT	2005/03/18 19:13		\$66
55	BRS	1088	(349/106,108).ccls.	US-PGPUB; USPAT	2005/03/18 19:13		\$60
56	BRS	1088	(349/106,108).ccls.	US-PGPUB; USPAT	2005/03/18 19:13		\$61
57	BRS	6393	(gate adj electrode) adj4 over (gate adj insulation adj layer)	USPAT	2005/03/18 19:13		\$63